
Cee[®] 1300CSX Thermal Debonder



Operator/User Manual

New users: Read this manual in its entirety before operating the equipment.

© 2019 Cost Effective Equipment, LLC



Contents

1. Products Covered in This Manual	3
2. Confidentiality Statement, Warranty, and Instructions for Returning Materials	3
2.1 Confidentiality Statement	3
2.2 Warranty	3
2.3 Instructions for Returning Materials	4
3. Introduction to the Cee® 1300CSX Thermal Debonder	5
3.1 Programmability	5
3.2 Precision	5
3.3 Reliability	5
3.4 Utilities	6
3.5 Dimensions	6
4. Software	7
4.1 Startup and Run Screen	7
4.1.1 Startup with Passwords Enabled	7
4.1.2 Home Slide Button	7
4.1.3 Run Screen	8
4.2 Debonding Process Screen	9
4.2.1 Running a Debonding Process	11
4.2.2 Loading a Substrate	12
4.2.3 Starting a Debonding Process	13
4.2.4 The Debonding Process Flow	13
4.2.5 Aborting a Process	15
4.2.6 Continuing a Process	15
4.3 Recipe Manager (Edit) Screen	16
4.3.1 Writing a Recipe	18
4.3.2 Entering Data	18
4.3.3 Recipe Management	19
4.3.4 Recipe Backup	20
4.4 Diagnostics Screen	21
4.4.1 Debonder Diagnostics Screen	22
4.5 User Configuration Screen	30
4.5.1 Debonder User Configuration Screen	32
4.5.2 Password Configuration Screen	34
4.5.3 User Level Access	34
4.6 Navigation Bar	35



1. Products Covered in This Manual

This manual covers the Cee® 1300CSX thermal slide debonder. This manual is to be used to install, operate, and troubleshoot the 1300CSX debonder. **New users should read this manual in its entirety before operating the equipment.**

2. Confidentiality Statement, Warranty, and Instructions for Returning Materials

2.1 Confidentiality Statement

Information supplied is only for use during operation and/or maintenance of Cee® equipment. **Neither this document nor the information it contains shall be disclosed to others for manufacturing or any other purpose without written authorization from Cost Effective Equipment, LLC.**

2.2 Warranty

Cost Effective Equipment, LLC (Cee), warrants to the original purchaser (Buyer) that the equipment is free from defects in material and workmanship under normal use and service in accordance with Cost Effective Equipment, LLC instructions and specifications.

Buyer shall promptly notify Cost Effective Equipment, LLC of any claim against this warranty, and any item to be returned to Cost Effective Equipment, LLC shall be sent with transportation charges prepaid by Buyer, clearly marked with a Return Material Authorization (RMA) number obtained from Cost Effective Equipment, LLC Customer Support. (See section 2.3.)

Cee®'s obligation under this warranty is limited to the repair or replacement, at Cee®'s option, of any equipment, component, or part that is determined by Cee® to be defective in material or workmanship. This obligation shall expire one (1) year after the initial shipment of the equipment from Cee®.

This warranty shall be void if:

- a) Any failure is due to the misuse, neglect, or improper installation of or accident to the equipment.
- b) Any major repairs or alterations are made to equipment by anyone other than a duly authorized representative of Cee®. Representatives of Buyer may be authorized to make repairs to the equipment without voiding warranty upon completion of the appropriate Cee® equipment training program.
- c) Replacement parts are used other than those made or recommended by Cee®.



COST EFFECTIVE EQUIPMENT, LLC MAKES NO OTHER WARRANTIES, EXPRESSED OR IMPLIED, WITH RESPECT TO EQUIPMENT. NO WARRANTY IS MADE AS TO THE MERCHANTABILITY OF THE EQUIPMENT NOR ITS FITNESS FOR ANY PARTICULAR PURPOSE. In no event shall Cee® be liable for consequential loss or damages, however caused. No person or representative of Cee® is authorized to assume for Cee® any liability in connection with Equipment nor to make any change to this warranty unless such change or modification is put in writing and signed by an authorized representative of Cee®.

This warranty shall be governed by the laws of the state of Missouri, U.S.A.

2.3 Instructions for Returning Materials

Any materials, parts, or equipment returned to Cost Effective Equipment Customer Support must be clearly labeled with a Return Material Authorization (RMA) number.

To obtain an RMA number, contact:

Cost Effective Equipment Customer Support
Telephone: (573) 466-4300
E-Mail: support@costeffectiveequipment.com
Web Address: <http://www.costeffectiveequipment.com>

Shipping information for use in returns with an RMA number:

Cost Effective Equipment, LLC
Attn: Equipment Customer Support
3703 HyPoint Blvd
Rolla, Missouri 65401
USA



3. Introduction to the 1300CSX Thermal Debonder

The Cee® 1300CSX thermal debonder enables high-temperature slide-off debonding of thinned wafers in a laboratory setting. This tool permits development engineers to complete the final step of thinned-full-wafer processing in a confidential developmental setting. Internal small-scale prototyping capability may be used to accelerate product development cycles and improve time to market for new ultrathin wafer technologies.

3.1 Programmability

- PC-controlled
- PC-based touch screen interface and display
- Full-color alphanumeric-capable graphical user interface (GUI)
- 250,000 process recipe programs onboard
- A virtually unlimited number of user-defined recipe program steps
- 0.1-second resolution for step times (max. step time: 9,999.9 seconds)
- Connectivity: USB/Ethernet port for communications for uploading/downloading process parameters with offline firmware standard (offline recipe number and steps unlimited)
- Security: Password protection option available at no charge

3.2 Precision

- Precision lower platen z-position control (closed-loop control/feedback): $\pm 0.5 \mu\text{m}$ accuracy
- Substrate sizes: 2 inches to 200 mm round
- Temperature resolution: 0.1°C
- Temperature range: ambient to 300°C

3.3 Reliability

- Total throughput < 200 mm: est. 8-14 WPH
- Total throughput \geq 200 mm: est. 4-8 WPH
- Wafer breakage: < 10% (\geq 90% process yield for compound semiconductor and silicon)
- System uptime: > 90% over a 12-month period
- MTBF (hours/cycles): > 600 hours, 6,000 cycles
- MTTR: < 24 hours (critical spare parts, as defined by Cee®, to be kept at customer site per Cee® field service standard working schedule)



3.4 Utilities

- Electrical: 208 V, single phase, 50/60 Hz, 6500 W
- Exhaust: 30 cfm
- Vacuum: 25 in Hg
- Nitrogen or CDA: 100 psi

3.5 Dimensions

- 49" W × 39.5" D × 52.5" H (125 cm W × 100 cm D × 133 cm H)
- Shipping weight: 187 kg



4. Software

4.1. Startup and Run Screen

4.1.1 Startup with Passwords Enabled

If the Cee® 1300CSX debonder tool has passwords enabled, the initial screen will only contain login and logout buttons.

To log in, press the Login button, to view the touch screen keyboard, and then enter your password. By default, the passwords for a Cee® 1300CSX tool are:

Super User Level: CEE
User Level: 1300CSX
Maintenance: DIAG

4.1.2 Home Slide Button

Once login is complete, or at startup if passwords are not enabled, the Home Slide button is visible. Pressing this button will move the slide to the home sensor at a high speed. Once the home sensor detects the bottom platen, the bottom platen will move off of the sensor and then back onto the sensor at a very slow speed. Once the x-axis slide has returned to its home position, the z-axis lift platform will return to its home position by moving up to the end of its stroke and then back to the zero position. Once the homing sequence is complete, the Run screen appears and a process may be run.

4.1.3 Run Screen

Once the slide has returned to its home position and the user has logged in (if enabled), the Run screen will appear.

From this screen, the user can go directly to the Debonding Process screen by pressing the Debonding Process button in the left-center of the screen. Navigating to other windows is also possible by using the navigation bar at the bottom of the screen.



4.2 Debonding Process Screen


The Debonding Process screen is used to run and monitor debonding processes using the Cee® 1300CSX tool's software.

The screenshot displays the 'Force Process' interface. At the top, it shows 'BSI' and the date/time '10/23/2014 1:39:19'. The 'Recipe Name' is 'RECIPE 1'. There are two buttons: 'Load 3' and 'Edit Recipe 4'. A table lists parameters: Time (5 s), Velocity (0.00 mm/s), Position (470.34 mm), Press Height (0.00 μm), and Force (0.00 lb). A checkbox 'Run as lot' is present. A large green 'Start Process 10' button is prominent. On the right, 'Status: Idle 2' is shown. Further right, 'Current: .11 A' (13) and 'Pressure: 50.3 psi' (14) are displayed. Temperature gauges show 'Lower 189.9 °C' (12) and 'Upper 189.3 °C', both with '0.0 InHg' below them. At the bottom, a navigation bar contains 'Run', 'Edit', 'Diag', 'Config', 'Help', and 'Back' buttons.

The controls and indicators found on the Debonding Process screen are listed below:

1. **Recipe Name:** The name of the currently loaded recipe
2. **Status:** Describes the current status of the debonding process
3. **Load button:** Navigates to the recipe selection screen (section 4.2.1) to select the process settings
4. **Edit Recipe button:** Navigates to the Debonding Process editor if a recipe is loaded. If a recipe is not loaded, navigates to the recipe selection screen (section 4.2.1).
5. **Time indicator:** Displays the current time remaining of the current process step. Not all process steps are time-based.
6. **Velocity indicator:** Shows the current speed of the lower platen
7. **Position indicator:** Shows the current position of the lower platen along the slide
8. **Press Height indicator:** Shows the current height of the bottom platen
9. **Force indicator:** Shows the current x-axis (lateral) force being applied at the bottom platen





10. Process button: The process button has three modes:

- a. **Start Process:** Starts the debonding process. The user will be prompted to load the substrate at the appropriate time.
- b. **Abort:** Aborts a currently running process.
- c. **OK:** Turns off the Process Complete alarm.

11. Run as lot check box: Checking this box will cause the tool to begin the same process as soon as the previous process was completed. Checking this box eliminates the need for the user to press Start Process a second time. This check box will only appear if the tool is set to Production Mode on the User Configuration screen (section 4.5).

12. Temperature and Vacuum display: Shows the current temperature and vacuum level of both platens.

13. Current display: Shows the current on the z-axis lift.

14. Pressure display: Shows the current system pressure.



4.2.1 Running a Debonding Process

The screenshot shows the 'Force Process' control interface. At the top, it displays 'BSI' and the date/time '10/23/2014 1:41:52'. Below this, the 'Recipe Name:' field is empty. There are two buttons: 'Load' (highlighted in yellow) and 'Edit Recipe'. The 'Status:' is 'Idle'. The parameters are as follows:

Time		s
Velocity	0.00	mm/s
Position	470.34	mm
Press Height	0.00	µm
Force	0.00	lb

There is a checkbox for 'Run as lot' which is unchecked. A large green 'Start Process' button is visible. On the right, there are two columns of data: 'Current: .11 A' and 'Pressure: 50.4 psi'. Below these are two temperature displays: 'Lower 190.0 °C' and 'Upper 190.0 °C', and two pressure displays: '0.0 InHg' and '0.0 InHg'. At the bottom, there is a navigation bar with buttons: 'Run' (highlighted in yellow), 'Edit', 'Diag', 'Config', 'Help', and 'Back'.

To run a debonding process, a recipe must first be loaded. Pressing the Load button will bring up the recipe selection screen (see below). To select a recipe, double-press on the desired recipe, or select the desired recipe and press Enter.

The screenshot shows the recipe selection screen. At the top, there is a 'Filter:' field and two radio buttons: 'Name' (selected) and 'Date'. Below this is a list of items:

- folder1
- folder2
- production
 - 1234
 - 4321


At the bottom, there are two buttons: 'ENTER' and 'CANCEL'.



4.2.2 Loading a Substrate

The Cee® 1300CSX tool will prompt the user to load a substrate at the appropriate time after the Start Process button is pressed. The process to load a substrate is as follows:

1. Place substrate on proper loading arm with the notch or flat to the right.
2. Insert loading arm with substrate into the alignment pocket on the lower platen at the angle shown below. Be sure the substrate does not move on the loading arm.
3. Rotate the arm forward until the substrate is lifted off the loading arm.
4. Carefully pull out loading arm without bumping the substrate.
5. Visually check that the substrate is centered.
6. Press Continue at the user prompt.



4.2.3 Starting a Debonding Process

The screenshot displays the 'Force Process' control interface. At the top, it shows 'BSI' and the date/time '10/23/2014 1:39:19'. The 'Recipe Name' is 'RECIPE'. Below this are two buttons: 'Load' and 'Edit Recipe'. A table of parameters is shown:

Time		s
Velocity	0.00	mm/s
Position	470.34	mm
Press Height	0.00	μm
Force	0.00	lb

The status is 'Idle'. There is a checkbox for 'Run as lot'. A large green 'Start Process' button is prominent. On the right, current and pressure are shown: 'Current: .11 A' and 'Pressure: 50.3 psi'. Below these are two temperature readouts: 'Lower 189.9 °C' and 'Upper 189.3 °C', and two vacuum readouts: '0.0 InHg' for both. At the bottom, there are navigation buttons: 'Run', 'Edit', 'Diag', 'Config', 'Help', and 'Back'.

Press the Start Process button to begin a debonding process. The tool will initiate a sequence of prompts to get the substrate successfully loaded onto the lift pins. This sequence is as follows:

1. Press the Start Process button.
The lower platen will go to home position and lift pins will rise.
The user will be prompted to load the substrate. See section 4.2.2.
2. Confirm loading by pressing OK on the prompt.
3. Wait for "Lift Pin Delay" from recipe.
Lift pins will lower.
4. Wait for "Pre Vac Delay" from recipe.
Vacuum is initiated, and the tool checks for substrate.
5. Wait for "Lower Plate Delay" from recipe.
6. Process begins.



4.2.4 The Debonding Process Flow

The flow of the debonding process is as follows:

1. The lower platen moves under the upper platen.
2. The lower platen moves up to the vacuum search window start position determined by “Stack Thickness” and “Search Distance.”
3. Upper platen vacuum is turned on.
4. The lower platen will continue to move up by increments specified by “Step Distance” in the recipe.
5. If vacuum is found on the upper platen, the lower platen will halt. If no vacuum is found, the lower platen will recover and move back to the loading position.
6. The process will wait for the time specified by thermal stabilization (Press Up) in the Recipe Manager screen.
7. The lower platen will then move toward the home position using the force specified in the recipe, limited by the maximum speed, which is also specified by the recipe.
8. Once the substrates have debonded, the lower platen will lower to its home position, and then the slide will return to the home position.
9. The user will be prompted to insert the extraction tool. When the sensor detects the extraction tool, the substrate on the upper platen will be released.
10. The user may then remove the substrate from the lift pins on the bottom platen.
11. The tool will ask the user to acknowledge when all extraction tools are clear of the Cee®1300CSX tool. This acknowledgment concludes the process.




4.2.5 Aborting a Process



After a process has started, pressing the Abort button, EMO, or breaking the light curtain will abort the process. Aborting a process will halt the Cee® 1300CSX tool in its current state and will allow the user to go into Diag mode and attempt manual debonding to save the substrate. When the EMO has been pressed, the Cee® 1300CSX tool must be restarted to appropriately recover.

4.2.6 Continuing a Process

A process can be aborted for several reasons (user abort, low vacuum, speed too high, force too high, light curtain broken, emergency off [EMO], etc.). If the process is aborted by either the user or the software, the tool will pause and offer the user a chance to continue or abort. If the user chooses to continue, the process will try to continue by ignoring hardware signals to abort; however, the Abort button will stay active. When the process continues, the software will ignore the recipe values for force and maximum speed and instead use the parameters specified in the Config screen (section 4.5.1).



This feature allows the user to enter safe values (lower Max Velocity and lower Force) to try to continue debonding a substrate stack after the process was aborted. The tool must be monitored during this portion of the run, however, because the tool will ignore further alarms such as the one for low vacuum.



4.3 Recipe Manager (Edit) Screen

To navigate to the Recipe Manager (Edit) screen, press the Edit button located on the lower navigation panel.

The screenshot shows the 'Recipe Manager' interface for 'Super User' on '10/2/2014 11:16:00'. The recipe name is 'RECIPE 1'. The interface is divided into several sections:

- Left Panel:** Contains three buttons: 'Load...2', 'Save...3', and 'Delete...4'.
- Wafer Size:** A dropdown menu set to '150mm' with a '5' indicator.
- Temperature Section:**
 - Upper:** Temp 190 °C (with a '6' indicator), Tolerance 5 °C (with a '7' indicator).
 - Lower:** Temp 190 °C (with an '8' indicator), Tolerance 5 °C (with a '9' indicator).
- Lift Pin Timing Section:**
 - Lift Pin Descent: 50 sec (with a '10' indicator)
 - Pre Vac: 10 sec (with an '11' indicator)
 - Lower Platen: 10 sec (with a '12' indicator)
- Force Section:** Force 4 lb (with a '13' indicator), Maximum Velocity 2 mm/s (with a '14' indicator).
- Press Control Section:**
 - Stack Thickness: 1380 μm (with a '15' indicator)
 - Search Distance: 100 μm (with a '16' indicator)
 - Step Distance: 2 μm (with a '17' indicator)
- Thermal Stabilization Section:** Press Up 30 sec (with an '18' indicator').

At the bottom, there is a navigation bar with buttons: 'Run', 'Edit', 'Diag', 'Config', 'Help', and 'Back'.

The controls and indicators found on the Recipe Manager (Edit) screen are listed below:

1. **Recipe Name:** The name of the currently loaded recipe
2. **Load button:** Opens the dialog to load a recipe into the editor
3. **Save button:** Opens the save dialog for saving the current recipe
4. **Delete button:** Opens the delete dialog for deleting recipes
5. **Substrate size dropdown menu:** A dropdown menu for selecting the substrate size (each Cee® 1300CSX tool may be configured for different sizes)
6. **Upper platen Temperature:** The temperature for the upper platen
7. **Upper platen Tolerance:** The temperature tolerance of the upper platen beyond which an error will occur
8. **Lower platen Temperature:** The temperature for the lower platen
9. **Lower platen Tolerance:** The temperature tolerance of the lower platen beyond which an error will occur



Recipe Manager Super User 10/2/2014 11:16:00

RECIPE Recipe Name: RECIPE 1

Wafer Size 150mm 5

Temperature

Upper Temp 190 6 °C Tolerance 5 7 °C

Lower Temp 190 8 °C Tolerance 5 9 °C

Lift Pin Timing

Thermal Stabilization

Lift Pin Descent 50 10 sec

Pre Vac 10 11 sec

Lower Platen 10 12 sec

Force

Force 4 13 lb

Maximum Velocity 2 14 mm/s

Press Control

Vacuum Search Window

Stack Thickness 1380 15 μm

Search Distance 100 16 μm

Step Distance 2 17 μm

Thermal Stabilization

Press Up 30 18 sec

Run Edit Diag Config Help Back

10. Lift Pin Descent: The time the lift pins will take to descend from their up position down to the platen

11. Pre Vac delay: The time the substrate will rest on the lower platen before vacuum is applied

12. Lower Platen delay: The time the substrate will rest on the lower platen before beginning the process

13. Force: The x-axis (lateral) force applied to the substrates for debonding

14. Maximum Velocity: The maximum speed the slide will operate even if the force specified in the recipe is not required

15. Stack Thickness: The thickness of the bonded substrates prior to debonding

16. Search Distance: The overall distance the lower platen moves while searching for vacuum on the upper platen

17. Vacuum Search Step Distance: The vertical distance the lower platen will rise between stopping to try to detect a vacuum

18. Press Up delay: The time that the Cee® 1300CSX tool will delay after finding vacuum on the upper platen before attempting to debond



4.3.1 Writing a Recipe

Recipes are entered in the Recipe Manager screen (accessible by pressing the Edit button in the bottom navigation bar), shown below.

The screenshot shows the 'Recipe Manager' interface. At the top, it displays 'Super User' and the date/time '10/2/2014 11:16:00'. The main title is 'Recipe Name: RECIPE'. On the left, there are three buttons: 'Load...', 'Save...', and 'Delete...'. The main area contains several sections of parameters:

- Wafer Size:** 150mm (dropdown menu)
- Temperature:**
 - Upper: Temp 190 °C, Tolerance 5 °C
 - Lower: Temp 190 °C, Tolerance 5 °C
- Force:** Force 4 lb, Maximum Velocity 2 mm/s
- Press Control:**
 - Vacuum Search Window: Stack Thickness 1380 μm, Search Distance 100 μm, Step Distance 2 μm
 - Thermal Stabilization: Press Up 30 sec
- Lift Pin Timing:**
 - Thermal Stabilization: Lift Pin 50 sec, Pre Vac 10 sec, Lower Platen 10 sec

At the bottom, there is a navigation bar with buttons: 'Run', 'Edit', 'Diag', 'Config', 'Help', and 'Back'.

4.3.2 Entering Data

By selecting the any text box (items 6 through 18 in the screen shown in section 4.3 above), a numeric pad will appear, as shown below.


The screenshot shows a numeric keypad interface. At the top, a yellow banner displays 'Valid range: 0 to 12000'. Below this, a text box contains the number '1234' and a red 'X' button. The keypad itself has the following layout:

7	8	9	BACKSPACE
4	5	6	DELETE
1	2	3	ENTER
-	0	.	

Using the numeric pad, the user can now enter the parameter for the selected step. The valid range for the specific type of value will be provided above the number pad. Once




the desired value is entered, pressing the ENTER key will close the numeric pad and return to the Recipe Manager screen with the selected value updated.



When the small arrow at the right of the wafer size selection box at the top of the window is clicked, a dropdown box will allow the user to select the correct wafer size.

4.3.3 Recipe Management

Recipes are managed by the Load, Save, and Delete buttons (items 2, 3, and 4 in the screen shown in section 4.3). To load a saved recipe, press the Load button, which will bring up the Recipe Select screen, as shown below.



The recipe can be loaded into the editor by pressing a recipe name and then pressing Enter, or by double-pressing a recipe name.

To delete a saved recipe, press the Delete button, which will also bring up the Recipe Select screen. The recipe can be deleted by pressing a recipe name and then pressing enter, or by double-pressing a recipe name.

To save a recipe, press the Save button, which will bring up an on-screen keyboard (see below) for entering the recipe name. Enter the desired recipe name using the keyboard, and then press the Enter key, which will save the recipe with the desired name.




4.3.4 Recipe Backup

Recipes are saved in comma separated value (.csv) format. The Cee® 1300CSX tool uses a Windows® operating system. The debonding recipes are saved in the **c:\Cee\Force** folder in the Windows® file system. To back up recipes, copy recipe files to a storage device via the front USB port. Alternatively, files can be transferred via the Ethernet port on the back of the tool. By default the Cee® 1300CSX tool is set up as IP address 192.168.1.1, and the recipe folder is shared as a network store.



4.4 Diagnostics Screen

The Diagnostics screen allows manual operation of most of the hardware on the Cee® 1300CSX debonding tool.




The controls and indicators found on the Diagnostics screen, shown above, are listed below:

1. **Debonder Diagnostics button:** Navigates to the Debonder Diagnostics screen
2. **Show Desktop button:** Minimizes the Cee® 1300CSX tool control software, which allows display of the Windows® desktop
3. **Exit button:** Closes the Cee® 1300CSX tool control software and exits to the Windows® desktop



4.4.1 Debonder Diagnostics Screen


The Debonder Diagnostics screen allows manual operation of most of the hardware on the Cee® 1300CSX tool. The controls are contained on three tabs.



The controls and indicators found on the **I/O** tab of the Debonder Diagnostics screen are listed below:

- Upper Platen Vac On and Off buttons:** Turn on or off the vacuum on the upper platen. The current state will be highlighted.
- Lower Platen Vac On and Off buttons:** Turn on or off the vacuum on the lower platen. The current state will be highlighted.
- Upper Platen N₂ On and Off buttons:** Turn on or off the nitrogen on the upper platen. The current state will be highlighted.
- Lower Platen N₂ On and Off buttons:** Turn on or off the nitrogen on the lower platen. The current state will be highlighted.
- Lift Pins Up and Down buttons:** Raise or lower the lift pins on the lower platen.
- Light Tree controls:** Set the color of the light tree to green, yellow, or red.
- Upper Platen vacuum display:** This box will be green if the current level of vacuum is higher than the level set in the configuration screen. This box will be red otherwise.





8. **Lower Platen vacuum display:** This box will be green if the current level of vacuum is higher than the level set in the configuration screen. This box will be red otherwise.
9. **EMO display:** This box will display green if the emergency off (EMO) state is not interrupted and it is safe to run. If the EMO is interrupted, the box will be red. The Cee® 1300CSX tool will not operate if this box is red.
10. **Light Curtain display:** This box will display green if the light curtain is not interrupted and it is safe to run. If the light curtain is interrupted, the box will be red. The Cee® 1300CSX tool will not operate if this box is red.
11. **Wafer Wand display:** This box will display green if the wafer wand is present under the upper platen. This box will be red otherwise.
12. **Upper platen ring toggle:** The upper platen has rings that allow the platen to accept different sizes of substrates. These toggle buttons control which ring sizes are active when the vacuum or N₂ is active. The standard sizes are:

- No size: 2-inch substrates
- Size 2: 3-inch substrates
- Size 3: 100-mm substrates
- Size 4: 125-mm substrates
- Size 5: 150-mm substrates
- Size 6: 200-mm substrates

The boxes will be highlighted in green when active.

13. **Lower platen ring toggle:** The lower platen has rings that allow the platen to accept different size substrates. These toggle buttons control which ring sizes are active when the vacuum or N₂ is active. The standard sizes are:



No size: 2-inch substrates
Size 2: 3-inch substrates
Size 3: 100-mm substrates
Size 4: 125-mm substrates
Size 5: 150-mm substrates
Size 6: 200-mm substrates

The boxes will be highlighted in green when active.






The controls and indicators found on the **Other Controls** tab of the Debonder Diagnostics screen are listed below:

1. **Upper Platen Setpoint:** The setpoint for the temperature on the upper platen
2. **Upper Platen Value:** The current temperature of the upper platen
3. **Lower Platen Setpoint:** The setpoint for the temperature on the lower platen
4. **Lower Platen Value:** The current temperature on the lower platen
5. **Temperature Set:** Writes the values in (1) and (3) to the temperature controllers and starts transitioning the platens to the new setpoints
6. **Z-Axis status display:** The vertical position and current load of the z-axis lift.
7. **Z-Axis stop servo button:** When the z-axis lift is moving, this button will be red and display STOP Servo. Pressing the red button will immediately stop the servo. If the servo is not moving, the button will be gray and display Servo Idle; pressing it will have no effect.
8. **Z-Axis Enabled button:** When the z-axis lift is enabled and has no faults, the button is green and displays Enabled. When a fault has occurred, the button will turn red and display Re-enable. Pressing the red button will clear all faults and re-enable the servo. When the button is green, pressing it will have no effect.
9. **Z-Axis Move To field and Set button:** Enter the desired height in the Move To field and press set to move the z-axis lift.





- 10. Z-Axis Jog:** Enter the desired jog distance into the Jog field. Press the up-arrow button to move up and the down-arrow button to move down the entered jog distance.
- 11. Upper Vac display:** The current vacuum level on the upper platen
- 12. Lower Vac display:** The current vacuum level on the lower platen
- 13. Servo Status display:** The current servo velocity, position, and droop
- 14. Stop Servo button:** When the servo is moving, this button will be red and display STOP Servo. Pressing the red button will immediately stop the servo. If the servo is not moving, the button will be gray and display Servo Idle; pressing it will have no effect.
- 15. Home Position button:** Quickly moves the lower platen on the slide to the home position
- 16. Press Position button:** Quickly moves the lower platen under the upper platen into the press position
- 17. Force/Position toggle button:** This button affects items 18, 19, 20, 21, and 22 shown in the screen above. This button toggles between Force and Position mode control of the slide. Force mode will move the slide at a constant force up to a maximum speed. Position mode will move the slide a specified jog distance at a constant speed.
- 18. Velocity of jog:** In position mode, the velocity for the jog. In force mode, the force for the jog.



Debonder Diagnostics Super User 10/2/2014 10:38:19

I/O Other Controls Setup

Platen Temperatures

Upper Platen Setpoint **1** 20 °C
 Upper Platen Value **2** 79.2 °C
 Lower Platen Setpoint **3** 20 °C
 Lower Platen Value **4** 76.0 °C

Set **5**

Z Axis

Actual Pos: .00 μm **6** I: -1.66 A

Servo Idle... **7** Enabled **8**

Move To 0 **9** μm Set

Jog ↓ 0 **10** μm ↑

Platen 11 0.0 **12** 0.1
 Vacuum Upper Vac Lower Vac

X Axis

.00 mm/s **13** 474.35 mm

Servo Idle... **14**

15 Home Pos **16** Press Pos

Velocity Jog **17** Switch to Force Mode

Velocity 20 **18** mm/s Accel 100 **19** mm/s²

Jog ← 10 **20** mm → **21** **22**

Run Edit Diag Config Help Back

19. Accel for jog: The acceleration for the jog in position mode. Enter the maximum velocity of the servo for the jog in force mode.

20. Distance to jog: The distance to jog in position mode; has no effect in force mode.

21. Left arrow/Start: In position mode, jogs the lower platen left the distance specified in the distance to jog field (20); in force mode, starts a force jog.

22. Right arrow/Stop: In position mode, jogs the lower platen right the distance specified in the distance to jog field (20); in force mode, stops a force jog.





The controls and indicators found on the **Setup** tab of the Debonder Diagnostics screen are listed below:

- 1. Home X Axis button:** Homes the lower platen on the slide. The lower platen will move away from the upper platen position until it finds the home position. Pressing this button will move the slide to the home sensor at a high speed. Once the home sensor detects the bottom platen, the bottom platen will move off the sensor and then back onto the sensor at a very slow speed.
- 2. Home Z Axis button:** Homes the lower platen lift. The lower platen will move up to its max position. The lower platen will then move back down until the home sensor has been tripped.
- 3. Home Lift Pins button:** Homes the lift pins. This will move the lift pins up and then back down until the home sensor detects the lift pins.
- 4. Wafer Thickness field and Set button:** Field for entering the thickness of the wafer being used for the Vacuum Search Start Routine; pressing set will store the number
- 5. Load Wafer/Set Start Search:** Pressing the Load Wafer button will raise the lift pins so that the wafer can be loaded. A prompt will appear when the wafer can be safely loaded. Once the lift pins are raised fully, the Load Wafer button will change to Set Start Search. Pressing the Set Start Search button will turn on the lower platen vacuum and lower lift pins. Once vacuum has been achieved, the lower platen will move to the press position and then move up slowly searching for vacuum on the upper platen. When vacuum is achieved on the upper platen, the z-axis position is recorded. The lower platen will move down, move to the home position, and raise the lift pins. The Vacuum Search Start Routine is then complete.






6. **Idle/Abort button:** This button is gray and displays Idle when the Vacuum Search Start Routine is not active. When the Vacuum Search Start Routine is run, the button will turn red and display Abort. Pressing this button will abort the routine and return the lower platen to the home position.
7. **Vacuum Start Search Status Display:** Displays the current z-axis position and the last recorded maximum position
8. **Lift Pin Descent and Set:** Field for entering a value into the Lift Pin Descent field; pressing set will move lift pins to that height



4.5 User Configuration Screen


The User Configuration screen allows the user to set parameters for the Cee® 1300CSX tool operation. Not all parameters are available to all user levels.



The controls and indicators found on the User Configuration screen are listed below:

- 1. Debonder Configuration button:** Navigates to the Debonder Configuration screen
- 2. Password Config button:** Navigates to the Password Configuration screen
- 3. Beep On Screen Press:** If this setting is checked, the screen will sound a slight beep whenever a control is pressed. This feature is designed to provide feedback while using the Cee® 1300CSX tool.
- 4. Alarm On Process Complete:** If this setting is checked, the tool will sound an alarm when a process is completed
- 5. Enable Passwords:** If this setting is checked, the tool will require a password to start. Using passwords also allows different users of different levels to access limited portions of the Cee® 1300CSX tool's software. If passwords are not enabled, the Cee® 1300CSX tool automatically logs in as a Super User. For information on logging in to the Cee® 1300CSX tool's software, see the Run screen (section 4.1.3).
- 6. Prompt for Log Filename:** If this box is checked, it will prompt the user to enter a filename for the log when running a process. If the box is not checked, it will use the date, time, and recipe name for the filename.





7. **Enable Production Mode:** Checking this box keeps the lift pins from going down between process jobs
8. **Revert button:** If changes made to the settings on this screen are not desired, pressing this button will revert back to saved settings
9. **Save button:** Saves all parameters on the screen



4.5.1 Debonder User Configuration Screen

The Debonder User Configuration screen allows the user to set parameters for the Cee® 1300CSX tool's operation. Not all parameters are available to all user levels.

The screenshot displays the 'Debonder User Configuration' interface. At the top, it shows 'Super User' and the date/time '10/2/2014 10:40:05'. The interface is divided into several sections:

- Temperature Setting:** Upper Temperature: 20 1 °C, Lower Temperature: 20 2 °C.
- Vacuum:** Sensor Level Upper: 10 3 InHg, Lower: 10 4 InHg; Error Level Yellow: 10 5 InHg, Red: 5 6 InHg; Pressure Alert: 20 7 PSI.
- Error Limits:** Force Maximum: 6 8 lbs, Speed Maximum: 15 9 mm/s.
- Press Position:** Position: -24869330 10 counts, with a 'Load Current Position' button showing 11.
- Process Continue Parameters:** Max Velocity: 0.2 12 mm/s, Force: 3 13 lbs.

At the bottom, there are buttons for 'Run', 'Edit', 'Diag', 'Config', 'Help', and 'Back'. Additionally, there are 'Revert 14' and 'Save 15' buttons.

The controls and indicators found on the Debonder User Configuration screen are listed below:

- 1. Upper Temperature setpoint:** The setpoint for the upper platen. This value will be loaded at startup.
- 2. Lower Temperature setpoint:** The setpoint for the lower platen. This value will be loaded at startup.
- 3. Vacuum sensor setpoint – Upper platen:** The setpoint for vacuum level on the upper platen. This setting is the amount of vacuum needed for the process to find vacuum and continue the process.
- 4. Vacuum sensor setpoint – Lower platen:** The setpoint for vacuum level on the lower platen. This setting is the amount of vacuum needed for the process to find vacuum and continue the process.
- 5. Vacuum Error level – Yellow alarm:** The setpoint to trigger a warning during the debonding process. If the vacuum on either platen falls to this level, the light tree will show yellow but the process will continue.
- 6. Vacuum Error level – Red alarm:** The setpoint to trigger an error during the debonding process. If the vacuum on either platen falls to this level, the light tree will show red and halt. A prompt will ask if the process should continue.



Debonder User Configuration		Super User	10/2/2014 10:40:05
Temperature Setting Upper Temperature: 20 1 °C Lower Temperature: 20 2 °C		Error Limits Force Maximum: 6 8 lbs Speed Maximum: 15 9 mm/s	
Vacuum Sensor Level Upper: 10 3 InHg Lower: 10 4 InHg Error Level Yellow: 10 5 InHg Red: 5 6 InHg		Press Position Position: -24869330 10 counts <input type="button" value="Load Current Position"/> 11	
Pressure Alert: 20 7 PSI		Process Continue Parameters Max Velocity 0.2 12 mm/s Force 3 lbs	
		<input type="button" value="Revert"/> 13 <input type="button" value="Save"/> 14	
<input type="button" value="Run"/>	<input type="button" value="Edit"/>	<input type="button" value="Diag"/>	<input type="button" value="Config"/>
		<input type="button" value="Help"/>	<input type="button" value="Back"/>

7. **Pressure Alert setpoint:** If the nitrogen/clean dry air (N₂/CDA) pressure falls below this setpoint, a warning message will appear
8. **Force Maximum level:** If the process exceeds this amount of force, the process will halt and prompt for whether or not it should continue
9. **Speed Maximum level:** If the process exceeds this speed, the process will halt and prompt for whether or not it should continue
10. **Press Position:** The position of the bottom platen along the slide where it will rise and contact the upper platen; this position must be correct for the process to work
11. **Load Current Position button:** Loads the current position of the lower platen into the Press Position field
12. **Process Continue Parameters:** If a process is aborted, the tool will allow the user to try to continue the process. These parameters (Max Velocity, Force) will be used instead of the ones in the recipe. This feature allows for use of safe values (slower speed and less force) so that continued processes will have the highest chance for success.
13. **Revert button:** If changes made to the settings on this screen are not desired, pressing this button will revert back to previously saved settings
14. **Save button:** Saves all parameters on the screen



4.5.2 Password Configuration Screen

The Password Configuration screen allows the user to change passwords.

User Level	New Password	Confirm New Password	
User	<input type="text"/>	<input type="text"/>	<input type="button" value="Update"/>
Super User	<input type="text"/>	<input type="text"/>	<input type="button" value="Update"/>
Maintenance	<input type="text"/>	<input type="text"/>	<input type="button" value="Update"/>

Run Edit Diag **Config** Help Back

The default passwords for the Cee® 1300CSX tool are:

Super User Level: CEE
User Level: 1300CSX
Maintenance: DIAG

To change a password, press the New Password box for the desired user level, and an on-screen keyboard will appear which allows the user to enter a new password. The on-screen keyboard will not display the password. Retype the new password in the Confirm New Password box. To save, press Update. If the entries in the New Password box and the Confirm New Password box match, the new password will be stored.

4.5.3 User Level Access

The level of access given to each different user level is:

Super User Level: Everything
User Level: Run screen
Maintenance: Run screen, Diagnostics screen, Configuration screen

By de-selecting the Enable Passwords option on the User Configuration screen, the Cee® 1300CSX tool's software will automatically log in at the Super User level.



4.6 Navigation Bar

The navigation bar enables quick navigation of the Cee® 1300CSX tool's software. The currently selected page is highlighted in white. The buttons on the navigation bar are listed below:



Run button: Navigates to the Run screen, which is where processes are run and monitored on the Cee® 1300CSX tool

Edit button: Navigates to the Edit screen, which is where processes are created, edited, and deleted on the Cee® 1300CSX tool

Diag button: Navigates to the Diagnostics screen. From here, the Cee® 1300CSX tool can be operated manually, allowing maintenance and diagnostics to be performed.

Config button: Navigates to the Configuration screen. All the user-configurable settings for the Cee® 1300CSX tool can be viewed or edited here.

Help button: Navigates to the Help page, which contains the User Manual

Back button: Returns to the previous screen

